




Montgomery Ward GEN-39500 Antenna Replacement

Written By: Dustin Platt



INTRODUCTION

The antenna receive an AM/FM radio signal. This guide will help you replace your antenna in case it is damaged.



TOOLS:

- [Soldering Station](#) (1)
 - [Phillips #2 Screwdriver](#) (1)
-

Step 1 — Back Cover





- Remove the nine 35 mm Phillips screws securing the back cover of the case.

Step 2




- Carefully remove the back cover.
- ⓘ Soldered wires connect electronics on the back cover to the internal electronics. Be careful not to break any connections.

Step 3




- Unplug the black and yellow wires connecting the power supply unit to the rest of the electronics:
- ⓘ This is not necessarily required. This step is to allow the back cover more movement as you work on the inside of the unit.

Step 4 — Antenna



- Unsolder the wire connecting the antenna to the radio.

Step 5



- Tilt the back cover up and remove the two 7.5 mm Phillips screws holding the antenna in place.

Step 6



- Remove the antenna.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-30 06:12:47 AM.